

CLASSIFIED MESSAGE

DATE 2315Z 19 JUN 1963

SECRET

ROUTING			
1	CD	4	DFE
2		5	DFE
3	MD	6	RB

TO DIRECTOR

25X1 FROM []

ACTION: OSA (1-15)

INFO: S/C (16)

ROUTINE

IN 80465

25X1 TOR: 0321Z 20 JUN 1963

TO []

INFO

CITE

[]

25X1

IDEALIST

SUBJ: ECP LAC-159

THE FOG SPO HAS DETERMINED THAT THIS CHANGE WILL BE REQUIRED FOR PERFORMANCE OF OTHER CHANGES BEING CONSIDERED. IN FACT THE ANTICIPATED PERFORMANCE OF THIS GENERATOR COULD BE MARGINAL IN THE VERY NEAR FUTURE.

REQUEST THE CONTRACTOR CONTACT VENDOR FOR THE PURPOSE OF IMPROVING OUTPUT OF THE UNIT. NEW BEARINGS, LUBRICANTS, AND SEALS MAY BE SUFFICIENT.

GENERATORS REMOVED FROM SERVICE PER THIS ECP WILL BE RETAINED FOR EMERGENCY SPARES.

REQUEST CONTRACTING OFFICER FORMALLY ADVISE CONTRACTOR OF SPO APPROVAL OF SUBJECT CHANGE WITH THE ADDED REQUIREMENTS STATED HEREIN.

END OF MESSAGE

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification